






 InSight Condition Report

2018 Chevrolet Bolt EV LT 4dr Car Hatchback

1G1FW6S03J4109841 2,917 mi | Front Wheel Drive | Electric Motor | A/T | Hard Top | Cloth
 Lane/Run 23/176 Facilitation Manheim Pennsylvania Seller TESLA MOTOR INC



				
Damages	No Structural Damage	No Prior Paint	Tires	Clean
				
Drivable	Starts	No Odor	Keys (Present)	Title? (No Data)



Announcements

- CHARGING CABLE MISSING
- CERTIFIED

High Value Options

- | | | | |
|------------------------|-------------------------|--------------------|----------------------------|
| • Back-Up Camera | • Heated Front Seat(s) | • Power Liftgate | • Smart Device Integration |
| • Blind Spot Monitor | • Heated Steering Wheel | • Rear Parking Aid | • Tire Pressure Monitor |
| • Bluetooth Connection | • HID headlights | • Satellite Radio | • WiFi Hotspot |
| • Climate Control | • Keyless Start | | |

Damage Overview



None ● ● ● Severe

● Structural Issue

Exterior (2)

Description	Condition Severity	Type	Image	Additional Info
● Windshield	Chipped < 1/8"	Miscellaneous		
● RF Door	Mult Dents/No Paint Dmg PDR/2	Cosmetic Conventional Paint and Body Not Required		

Interior (3)

Description	Condition Severity	Type	Image	Additional Info
● Warranty Books	Missing Replacement Required	Miscellaneous		
● Owners manuals	Missing Replacement Required	Miscellaneous		
● Maintenance Book	Missing Replacement Required	Miscellaneous		

Structure (0)

No structural damages reported

Other (0)


No other damages reported

Tires & Wheels

Wheels Aluminum

Left Front
 MICHELIN
6/32"
 215/50R17.0

Left Rear
 MICHELIN
7/32"
 215/50R17.0



Right Front
 MICHELIN
6/32"
 215/50R17.0

Right Rear
 MICHELIN
7/32"
 215/50R17.0

Spare
 (None)
0/32"

- 6/32 +
- 5/32 to 4/32
- < 4/32
- N/A

History



No. of Historical Events	3
Calculated Owners	1
Last Reported Mileage	2,917
Calculated Accidents	0

Title and Problem Check ✔ Vehicle checks out!

Odometer Check ✔ Vehicle checks out!

Use and Event Check ⚠ Vehicle Use or Event information available

AutoCheck Buyback Protection ✔ Qualifies

CARFAX

[View CARFAX](#)

Details

Exterior Color Silver	Title State NY	Work Order 5870875
Interior Color Dark Galvanized/Sky Cool Gray	Title Received 10/05/2018	In Service Date Not Available
Top Type Hard Top	Received Date 08/30/2018	Org Mfg Basic Warranty *3 Years/36,000 Miles *Manheim is not responsible for voided warranties
MSRP Not Available	Inspection Location Manheim Pennsylvania	

Equipment

Options

- A/C
- Adjustable Steering Wheel
- AM/FM Stereo
- Auto-Dimming Rearview Mirror
- Automatic Headlights
- Auxiliary Audio Input
- Bucket Seats
- Cargo Shade
- Child Safety Locks
- Cruise Control
- Daytime Running Lights
- Driver Air Bag
- Driver Vanity Mirror
- Engine Immobilizer
- Floor Mats
- Front Head Air Bag
- Front Side Air Bag
- Heated Mirrors
- Intermittent Wipers
- Keyless Entry
- Knee Air Bag
- Leather Steering Wheel
- MP3 Player
- Pass-Through Rear Seat
- Passenger Air Bag
- Passenger Air Bag Sensor
- Passenger Vanity Mirror
- Power Door Locks
- Power Mirror(s)
- Power Steering
- Power Windows
- Rear Bench Seat
- Rear Defrost
- Rear Floor Mats
- Rear Head Air Bag
- Rear Side Air Bag
- Remote Engine Start
- Remote Trunk Release
- Security System
- Stability Control
- Steering Wheel Audio Controls
- Telematics
- Tow Hooks
- Traction Control
- Variable Speed Intermittent Wipers

Interior

- Cloth
- Odometer Operable

Mechanical

- ABS Brakes
- Automatic Transmission
- Electric Fuel System
- Electric Motor
- Front Wheel Drive

Keys

- Master - 2

Manufacturer Info

Manufacturer Package Information

Information set forth herein is based solely on information provided by the vehicle manufacturer at the time of manufacture and may not be accurate or complete. Manheim has not undertaken steps to confirm the accuracy of any such information, and any information disclosed herein is provided "as is".

Packages

COMFORT AND CONVENIENCE PACKAGE - WPU

- (KI3) Automatic Heated Steering Wheel
- (N34) 3-Spoke Leather-Wrapped Steering Wheel And (DD8) Auto-Dimming Inside Rearview Mirror
- Includes (KA1) Heated Driver And Front Passenger Seats

DRIVER CONFIDENCE PACKAGE - WPR

- (UFG) Rear Cross-Traffic Alert And (UD7) Rear Parking Assist
- Includes (UKC) Lane Change Alert With Side Blind Zone Alert

Options

Other

- LPO, BLACK BOWTIE EMBLEMS, FRONT AND REAR
- REAR PARKING ASSIST
- REAR CROSS-TRAFFIC ALERT
- ELECTRIC DRIVE UNIT, (200 HP [150 KW] 266 LB-FT OF TORQUE [360 N-M])
- NIGHTFALL GRAY METALLIC
- GRILLE, BLACK
- LICENSE PLATE BRACKET, FRONT MOUNTING
- EMISSIONS, CALIFORNIA ZEV
- ENGINE, NONE
- LT PREFERRED EQUIPMENT GROUP
- WHEELS, 17" (43.2 CM) PAINTED ALUMINUM
- TIRES, P215/50R17 ALL-SEASON BLACKWALL, MICHELIN SELFSEAL PUNCTURE-SEALING
- SEATS, FRONT BUCKET
- DARK GALVANIZED/SKY
- COOL GRAY, DELUXE CLOTH SEAT TRIM
- AUDIO SYSTEM, CHEVROLET MYLINK RADIO
- DC FAST CHARGING
- SEATS, HEATED DRIVER AND FRONT PASSENGER
- STEERING WHEEL, 3-SPOKE LEATHER-WRAPPED
- STEERING WHEEL, HEATED
- MIRROR, INSIDE REARVIEW AUTO-DIMMING
- LANE CHANGE ALERT WITH SIDE BLIND ZONE ALERT
- EMISSIONS, CONNECTICUT, DELAWARE, MAINE, MARYLAND, MASSACHUSETTS, NEW JERSEY, NEW YORK, OREGON, PENNSYLVANIA, RHODE ISLAND, VERMONT AND WASHINGTON STATE REQUIREMENTS

Vehicle condition reports contain representations made by the seller and subjective input based on inspector judgment, which may affect any AutoGrade score. The use of the report and any AutoGrade score is subject to the Manheim Terms and Conditions and the NAAA Generic Condition Report Position Statement.

This grade was calculated under the assumption that some repairs may be covered under manufacturer warranty.

† Damage Overview diagrams are not an exhaustive representation of vehicle damage and should be viewed in conjunction with the damage detail list on each tab.

*Process protected under U.S. Patent No. 8,320,362

VIN: 1G1FW6S03J4109841,

Work Order: 5870875

© 2018 Manheim. All Rights Reserved

[Return to the classic CR](#)