

InSight Condition Report

2015 Nissan LEAF 4dr HB S

1N4AZ0CP2FC323370 25,981 mi | Front Wheel Drive | Electric Motor | A/T | Hard Top | Cloth
Lane/Run 2/115 Facilitation Manheim San Francisco Bay Seller NISSAN-INFINITI LT



AUTOGRADE
4.3
Clean

Damages	No Structural Damage	No Prior Paint	Tires	Clean
Drivable	Starts	No Odor	Keys 2	Fobs 0
Title? (No Data)				



Announcements

- DMV\$BP/CHARGER PKG
- QC**BC=12OF12
- WSD 07/23/2015

High Value Options

- | | | |
|------------------------|-------------------------|-------------------------|
| • Back-Up Camera | • Heated Front Seat(s) | • Keyless Start |
| • Bluetooth Connection | • Heated Rear Seat(s) | • Satellite Radio |
| • Climate Control | • Heated Steering Wheel | • Tire Pressure Monitor |

Damage Overview



None ● ● ● Severe

● Structural Issue

Exterior (9)

Description	Condition Severity	Type	Image	Additional Info
● Front Bumper Cover	Dent/Paint Dmg 1" to 2"	Paint and Body Requires Conventional Repair		
● F Bumper Center Grille-Screen	Loose Repair Required	Miscellaneous		
● Left Drip Rail	Scratch Light GR 12"	Paint and Body Requires Conventional Repair		
● LF Wheel Cover	Curb Rash 1" to 2"	Miscellaneous		
● LR Wheel Cover	Curb Rash 1/2" to 1"	Miscellaneous		
● RR Wheel Cover	Curb Rash 1" to 2"	Miscellaneous		
● RR Tire	Mismatched None	Miscellaneous		
● R Qtr Panel	Dent/No Paint Dmg PDR/1	Cosmetic Conventional Paint and Body Not Required		
● RF Wheel Cover	Bent Replacement Required	Miscellaneous		

Interior (0)

No interior damages reported

Structure (0)

No structural damages reported

Other (0)


No other damages reported

Tires & Wheels

Wheels Steel

Left Front
BRIDGESTONE
5/32"
205/55R16.0

Left Rear
BRIDGESTONE
7/32"
205/55R16.0



Right Front
BRIDGESTONE
4/32"
205/55R16.0

Right Rear
HANKOOK
9/32"
205/55R16.0

Spare
(None)
0/32"

- 6/32 +
- 5/32 to 4/32
- < 4/32
- N/A

History



No. of Historical Events 7
 Last Reported Event Date 02/15/2019
 Calculated Owners 1
 Last Reported Mileage 25,981
 Calculated Accidents 0

- Title and Problem Check ✔ Vehicle checks out!
- Odometer Check ✔ Vehicle checks out!
- Use and Event Check ! Specific vehicle use(s) or events reported
- AutoCheck Buyback Protection ✔ Qualifies

CARFAX

[View CARFAX](#)

Details

Exterior Color
Gun Metallic



Interior Color
Black

Top Type
Hard Top

Category Code
M

MSRP
Not Available

Title State
CA

Title Received
02/01/2019

Received Date
01/29/2019

Inspection Location
Manheim San Francisco
Bay

Work Order
2335534

In Service Date
Not Available

Org Mfg Basic Warranty
*3 Years/36,000 Miles
*Manheim is not
responsible for voided
warranties

Equipment

Options

- A/C
- Adjustable Steering Wheel
- AM/FM Stereo
- Auxiliary Audio Input
- Brake Assist
- Bucket Seats
- CD Player
- Child Safety Locks
- Cruise Control
- Driver Air Bag
- Driver Vanity Mirror
- Engine Immobilizer
- Front Head Air Bag
- Front Side Air Bag
- Heated Mirrors
- Intermittent Wipers
- Keyless Entry
- Leather Steering Wheel
- MP3 Player
- Pass-Through Rear Seat
- Passenger Air Bag
- Passenger Air Bag Sensor
- Passenger Vanity Mirror
- Power Door Locks
- Power Mirror(s)
- Power Steering
- Power Windows
- Rear Bench Seat
- Rear Defrost
- Rear Head Air Bag
- Rear Spoiler
- Security System
- Stability Control
- Steering Wheel Audio Controls
- Tire Inflator
- Traction Control
- Trip Computer
- Variable Speed Intermittent Wipers

Interior

- Cloth
- Odometer Operable

Mechanical

- 0.0L None
- ABS Brakes
- Automatic Transmission
- Electric Fuel System
- Electric Motor
- Front Wheel Drive

Keys

- Smart - 2

Manufacturer Info

Manufacturer Package Information

Information set forth herein is based solely on information provided by the vehicle manufacturer at the time of manufacture and may not be accurate or complete. Manheim has not undertaken steps to confirm the accuracy of any

such information, and any information disclosed herein is provided "as is".

Options

Interior

- 60-40 Folding Bench Front Facing Heated Fold Forward Seatback Cloth Rear Seat
- Manual Tilt Steering Column
- Gauges -inc: Speedometer, Odometer, Traction Battery Level, Power/Regen, Traction Battery Temperature, Trip Odometer And Trip Computer
- Power Rear Windows
- Heated Leather Steering Wheel
- Proximity Key For Doors And Ignition
- Remote Keyless Entry w/Integrated Key Transmitter, Illuminated Entry, Illuminated Ignition Switch And Panic Button
- Cruise Control w/Steering Wheel Controls
- Automatic Air Conditioning
- Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Auxiliary Mirror
- Engine Immobilizer
- Power 1st Row Windows w/Driver 1-Touch Up/Down
- Trip Computer
- Power Door Locks w/Autolock Feature
- Perimeter Alarm
- Cloth Front Seats w/Cloth Back Material
- Heated Front Bucket Seats -inc: 6-Way Manual Driver And 4-Way Manual Front Passenger Seats

Entertainment

- Radio: AM/FM/Single In-Dash CD/MP3/WMA -inc: Display Audio w/4.3" Color LCD Display, CD-Rom Playback Capability, Auxiliary Input Jack And USB Connection Port For iPod And Other Devices, XM Satellite Radio And 4-Speakers
- Bluetooth Wireless Phone Connectivity
- Radio w/Seek-Scan, Clock, Speed Compensated Volume Control, Steering Wheel Controls And External Memory Control

Safety/Security

- ABS Traction Control
- Dual Stage Driver And Passenger Front Airbags
- Low Tire Pressure Warning
- Airbag Occupancy Sensor
- Electronic Stability Control (Esc)
- Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- Curtain 1st And 2nd Row Airbags
- Rear Child Safety Locks

Exterior

- Variable Intermittent Wipers
- Lip Spoiler
- Tailgate/Rear Door Lock Included w/Power Door Locks
- Auto Off Aero-Composite Halogen Headlamps
- Wheels: 16" Steel w/Covers
- Tires: P205/55R16
- Body-Colored Power Heated Side Mirrors w/Manual Folding
- Fixed Rear Window w/Fixed Interval Wiper And Defroster

Mechanical

- Engine: 80kW AC Synchronous Motor
- Transmission: Single Speed Reducer
- Front-Wheel Drive
- Electric Power-Assist Speed-Sensing Steering
- Regenerative 4-Wheel Disc Brakes w/4-Wheel ABS, Front And Rear Vented Discs, Brake Assist And Hill Hold Control

Other

- Splash Guards
- 50 State Emissions
- Charge Package
- Floor Mats & Cargo Area Mat
- Hologram Kick Plates
- Activation Disclaimer

- Rear Camera

Vehicle condition reports contain representations made by the seller and subjective input based on inspector judgment, which may affect any AutoGrade score. The use of the report and any AutoGrade score is subject to the Manheim Terms and Conditions and the NAAA Generic Condition Report Position Statement.

This grade was calculated under the assumption that some repairs may be covered under manufacturer warranty.

† Damage Overview diagrams are not an exhaustive representation of vehicle damage and should be viewed in conjunction with the damage detail list on each tab.

*Process protected under U.S. Patent No. 8,320,362

VIN: 1N4AZ0CP2FC323370,

Work Order: 2335534

© 2019 Manheim. All Rights Reserved

[Return to the classic CR](#)