

InSight Condition Report

2015 Kia Soul EV 5dr Wgn +

KNDJX3AE6F7002864 25,940 mi | Front Wheel Drive | Electric Motor | A/T | Hard Top | Leather
Lane/Run 2/207 Facilitation Manheim San Francisco Bay Seller KIA MOTORS FINANCE



Damages	No Structural Damage	Prior Paint	Tires	Clean
Drivable	Starts	No Odor	Keys 2	Fobs 0 Title? (No Data)



Announcements

- DMV\$BP

High Value Options

- | | | | |
|------------------------|---------------------------------|--------------------------------|-------------------------|
| • Back-Up Camera | • Hard Disk Drive Media Storage | • Multi-Zone A/C | • Rear Parking Aid |
| • Bluetooth Connection | • Heated Front Seat(s) | • Navigation System | • Satellite Radio |
| • Climate Control | • Heated Rear Seat(s) | • Plug-In Electric Fast Charge | • Tire Pressure Monitor |
| • Cooled Front Seat(s) | • Heated Steering Wheel | • Premium Sound System | |
| • Fog Lamps | • Keyless Start | • Privacy Glass | |



Damage Overview



None ● ● ● Severe

● Structural Issue

Exterior (15)

Description	Condition Severity	Type	Image	Additional Info
● Front Bumper Spoiler	Curb Rash 2" to 3"	Miscellaneous		
● Front Bumper Cover	Scratch Heavy 1" to 2"	Paint and Body Requires Conventional Repair		
● Front Bumper Cover	Scratch Light 1" to 2"	Cosmetic Conventional Paint and Body Not Required		
● LF Door	Dent/No Paint Dmg PDR/1	Cosmetic Conventional Paint and Body Not Required		
● LF Door Edge	Scratch Heavy 1" to 2"	Miscellaneous		
● LF Fender	Dent/No Paint Dmg PDR/1	Cosmetic Conventional Paint and Body Not Required		
● LR Door	Dent/No Paint Dmg PDR/1	Cosmetic Conventional Paint and Body Not Required		
● Rear Bumper Cover	Mult Dents/Paint Dmg 2	Included Repairs fixed with Panel Repairs		
● Rear Bumper	Prev Repair SubStd Wavy	Previous Repair		
● Lift Gate	Chipped 8	Cosmetic Conventional Paint and Body Not Required		
● Lift Gate	Scratch Light 4" to 5"	Cosmetic Conventional Paint and Body Not Required		

Description	Condition Severity	Type	Image	Additional Info
● RF Door	Scratch Light 1/8" to 1/2"	Cosmetic Conventional Paint and Body Not Required		
● RF Fender	Dent/No Paint Dmg PDR/1	Cosmetic Conventional Paint and Body Not Required		
● RF Fender	Scratch Heavy 1" to 2"	Cosmetic Conventional Paint and Body Not Required		
● RF Fender	Scratch Light 5" to 6"	Cosmetic Conventional Paint and Body Not Required		

Interior (9)

Description	Condition Severity	Type	Image	Additional Info
● LF Door Panel	Stained Permanent	Interior		
● LF Seat	Stained Permanent	Interior		
● LR Seat Cushion	Stained Permanent	Interior		
● Rear Seat Center Back	Stained Permanent	Interior		
● RR Seat/2nd Row	Stained Permanent	Interior		
● RF Seat	Stained Permanent	Interior		
● Headliner	Stained Permanent	Interior		
● Left Sun Visor	Stained Permanent	Miscellaneous		
● Warning - Tire Pressure	On Unacceptable	Miscellaneous		

Structure (0)

No structural damages reported

Other (0)


No other damages reported

Tires & Wheels

Wheels Aluminum

Left Front
GENERIC
6/32"
205/60R16.0

Left Rear
GENERIC
8/32"
205/60R16.0



Right Front
GENERIC
6/32"
205/60R16.0

Right Rear
GENERIC
8/32"
205/60R16.0

Spare
(Compact)
N/A

- 6/32 +
- 5/32 to 4/32
- < 4/32
- N/A

History



No. of Historical Events 7

Last Reported Event Date 03/15/2019

Calculated Owners 1

Last Reported Mileage 25,940

Calculated Accidents 0

- Title and Problem Check ✔ Vehicle checks out!
- Odometer Check ✔ Vehicle checks out!
- Use and Event Check ! Specific vehicle use(s) or events reported
- AutoCheck Buyback Protection ✔ Qualifies

CARFAX

[View CARFAX](#)

Details

Exterior Color
Shadow Black w/Inferno
Red Roof



Interior Color
Gray 2-Tone

Top Type
Hard Top

MSRP
Not Available

Title State
CA

Title Received
02/21/2019

Received Date
02/27/2019

Inspection Location
Manheim San Francisco
Bay

Work Order
2341382

In Service Date
Not Available

Org Mfg Basic Warranty
*5 Years/60,000 Miles
*Manheim is not
responsible for voided
warranties

Equipment

Options

- A/C
- Adjustable Steering Wheel
- AM/FM Stereo
- Auto-Dimming Rearview Mirror
- Automatic Headlights
- Auxiliary Audio Input
- Brake Assist
- Bucket Seats
- Cargo Shade
- Child Safety Locks
- Cruise Control
- Daytime Running Lights
- Driver Air Bag
- Driver Illuminated Vanity Mirror
- Driver Vanity Mirror
- Floor Mats
- Front Head Air Bag
- Front Side Air Bag
- Heated Mirrors
- Intermittent Wipers
- Keyless Entry
- Leather Steering Wheel
- MP3 Player
- Pass-Through Rear Seat
- Passenger Air Bag
- Passenger Air Bag Sensor
- Passenger Illuminated Visor Mirror
- Passenger Vanity Mirror
- Power Door Locks
- Power Folding Mirrors
- Power Mirror(s)
- Power Steering
- Power Windows
- Rear Bench Seat
- Rear Defrost
- Rear Floor Mats
- Rear Head Air Bag
- Security System
- Stability Control
- Steering Wheel Audio Controls
- Traction Control
- Trip Computer
- Variable Speed Intermittent Wipers

Interior

- Leather
- Odometer Operable

Mechanical

- 0.0L None
- ABS Brakes
- Automatic Transmission
- Electric Fuel System
- Electric Motor
- Front Wheel Drive

Keys

- Smart - 2

Manufacturer Info

Manufacturer Package Information

Information set forth herein is based solely on information provided by the vehicle manufacturer at the time of manufacture and may not be accurate or complete. Manheim has not undertaken steps to confirm the accuracy of any such information, and any information disclosed herein is provided "as is".

Options

Interior

- Gauges -inc: Speedometer, Odometer, Traction Battery Level, Power/Regen, Trip Odometer And Trip Computer
 - Smart Device Integration
 - Power Rear Windows And Fixed 3rd Row Windows
 - Power 1st Row Windows w/Driver And Passenger 1-Touch Up/Down
 - Power Door Locks w/Autolock Feature
 - Heated Leather Steering Wheel
 - Remote Entry w/Integrated Key Transmitter
 - Proximity Key For Doors And Push Button Start
 - Trip Computer
 - Cruise Control w/Steering Wheel
- Controls
 - Manual Tilt/Telescoping Steering Column
 - Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination
 - Folding Cargo Cover
 - Ventilated Front Bucket Seats
 - Day-Night Auto-Dimming Rearview Mirror
 - 60-40 Folding Bench Front Facing Heated Fold Forward Seatback Rear Seat
 - Integrated Navigation System w/Voice Activation
 - Dual Zone Front Automatic Air Conditioning
 - Pure Leather Seat Trim -inc: Blue Piping

Entertainment

- Radio w/Seek-Scan, MP3 Player, Clock, Speed Compensated Volume Control, Steering Wheel Controls, Voice Activation And Internal Memory
- Bluetooth Wireless Phone Connectivity
- Radio: UVO EV Services Infotainment -inc: 8" Screen, Charge Station Locator, Battery Status Info, Appointed Charging, Appointed Ventilation, Energy Usage, Eco Driving Display, 911 Connect, Roadside Assistance, EV Services Guide, Climate Schedules, Pandora, Downloadable apps And Siri Eyes Free, Navigation

Safety/Security

- Back-Up Camera
- Electronic Stability Control (Esc)
- Rear Child Safety Locks
- Dual Stage Driver And

Exterior

- Fixed Rear Window w/Fixed Interval Wiper And Defroster
- Deep Tinted Glass
- Variable Intermittent Wipers
- Tailgate/Rear Door Lock Included w/Power Door Locks
- Front Fog Lamps
- Fully Automatic Projector Beam Halogen Daytime Running Headlamps w/Delay-Off
- Body-Colored Power Heated Side Mirrors w/Power Folding
- Wheels: 16" Alloy w/Full Wheel Covers
- Tires: 16"

Mechanical

- Engine: 109HP AC Electric Motor
- Transmission: 1-Speed Automatic
- Front-Wheel Drive
- Regenerative 4-Wheel Disc Brakes w/4-Wheel ABS, Front Vented Discs, Brake Assist, Hill Hold Control And Electric Parking Brake
- Lithium Ion Traction Battery w/6.6 kW Onboard Charger, 24 Hrs Charge Time @ 110/120V, 5 Hrs Charge Time @ 220/240V and 0.5 Hr Charge Time @ 440V
- Electric Power-Assist Speed-Sensing Steering

Other

- Black Interior Package
- Carpeted Floor Mats

- ABS And Driveline Traction Control
- Passenger Front Airbags
- Wheel Locks
- Low Tire Pressure Warning
- Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- Curtain 1st And 2nd Row Airbags
- Front And Rear Parking Sensors
- Airbag Occupancy Sensor

Vehicle condition reports contain representations made by the seller and subjective input based on inspector judgment, which may affect any AutoGrade score. The use of the report and any AutoGrade score is subject to the Manheim Terms and Conditions and the NAAA Generic Condition Report Position Statement.

This grade was calculated under the assumption that some repairs may be covered under manufacturer warranty.

† Damage Overview diagrams are not an exhaustive representation of vehicle damage and should be viewed in conjunction with the damage detail list on each tab.

*Process protected under U.S. Patent No. 8,320,362

VIN: KNDJX3AE6F7002864,
Work Order: 2341382

© 2019 Manheim. All Rights Reserved

[Return to the classic CR](#)