



Learn More

Manheim Digital Marketplace
 Condition Report
 Atlanta, GA 30328
 (866)626-4346

VEHICLE DETAILS - 2017 NISSAN LEAF S

VIN: 1N4BZ0CP3HC307735	Body Style: 4DHB	Top Type: Hard Top
Ext Color: GREY	Int Color: Bla- BLK	Odometer: 16,988
Work Order: 4060483	Seller: NISSAN MOTOR CORPORATION	Received Date: N/A
InService Date: N/A		



GRADING



Grade 4.5 Clean

- MSRP-0 ???.
- Drivable-Yes

*Process protected under U.S. Patent No. 8,320,362

VALUE ADDED OPTIONS

- Bluetooth Connection
- Heated Seats-Front(s)
- Satellite Radio
- CD Changer
- MP3 Compatible Stereo

VEHICLE INFORMATION

OPTIONS

- | | | | |
|------------------------|--------------------------------|--------------------------------|--------------------|
| ■ A/C | ■ Child Safety Locks | ■ Power Mirrors | ■ Traction Control |
| ■ ABS Brakes | ■ Cruise Control | ■ Power Windows | ■ Trip Computer |
| ■ AM/FM Stereo | ■ Electronic Stability Control | ■ Pwr Steering | ■ Wheel Covers |
| ■ Automatic Headlights | ■ Engine Immobilizer | ■ Rear Floor Mats | |
| ■ Back up Camera | ■ Front Floor Mats | ■ Rear Spoiler | |
| ■ Brake Assist System | ■ Intermittent Wipers | ■ Security System | |
| ■ Bucket Seats | ■ Keyless Entry | ■ Steering Wheel Audio Control | |
| ■ CD Player | ■ Keyless Start | ■ Tilt Steering | |
| ■ Cargo Shade | ■ Pass-Through Rear Seat | ■ Tire Pressure Monitor System | |

MECHANICAL

- Engine Type - Non
- Automatic
- 4X2

INTERIOR

- Odometer - 6 Digits Digital -Operable
- Cloth - BLK
- Int Odor: OK

TIRES AND WHEELS

Wheels:

Tire	Tread Depth	Brand	Size
Left Front:	7/32"	Bridgestone	205/55R16
Left Rear:	7/32"	Bridgestone	205/55R16
Right Front:	7/32"	Bridgestone	205/55R16
Right Rear:	7/32"	Bridgestone	205/55R16
Spare:	10/32"	Other	255/30R18

KEYS

- Remote Key/Fob - 2

OTHER

- Title State:
- Title Received Date: N/A

ADDITIONAL INFORMATION

DAMAGE SUMMARY AND ADDITIONAL IMAGES

Open All Damages Close All Damages


Cosmetic Conventional Paint and Body Not Required-[1 Items]


IMAGE	DESCRIPTION	CONDITION	SEVERITY
	Rear Bumper	Prev Repair	Acceptable


Previous Repair-[1 Items]


IMAGE	DESCRIPTION	CONDITION	SEVERITY
	Deck Lid	Prev Repair	Acceptable


IMAGE	DESCRIPTION	CONDITION	SEVERITY
-------	-------------	-----------	----------


	0000 Picture# 1	Overall Picture	
--	-----------------	-----------------	--


	0000 Picture# 2	Overall Picture	
--	-----------------	-----------------	--


	0000 Picture# 3	Overall Picture	
--	-----------------	-----------------	--


	0000 Picture# 4	Overall Picture	
--	-----------------	-----------------	--


	0000 Picture# 5	Overall Picture	
--	-----------------	-----------------	--


	0000 Picture# 6	Overall Picture	
---	-----------------	-----------------	--


	0000 Picture# 7	Overall Picture	
--	-----------------	-----------------	--


	0000 Picture# 8	Overall Picture	
--	-----------------	-----------------	--


	0000 Picture# 9	Overall Picture	
--	-----------------	-----------------	--


	0000 Picture# 10	Overall Picture	
--	------------------	-----------------	--


	0000 Picture# 11	Overall Picture	
--	------------------	-----------------	--


	0000 Picture# 12	Overall Picture	
--	------------------	-----------------	--

	0000 Picture# 13	Overall Picture	
--	------------------	-----------------	--

	0000 Picture# 14	Overall Picture	
--	------------------	-----------------	--

	0000 Picture# 15	Overall Picture	
--	------------------	-----------------	--

	0000 Picture# 16	Overall Picture	
--	------------------	-----------------	--

	0000 Picture# 17	Overall Picture	
--	------------------	-----------------	--

	0000 Picture# 18	Overall Picture	
--	------------------	-----------------	--



0000 Picture# 19	Overall Picture
0000 Picture# 20	Overall Picture
0000 Picture# 21	Overall Picture
0000 Picture# 22	Overall Picture
0000 Picture# 23	Overall Picture
0000 Picture# 24	Overall Picture
0000 Picture# 25	Overall Picture

MANUFACTURER PACKAGE INFORMATION

INFORMATION SET FORTH HEREIN IS BASED SOLELY ON INFORMATION PROVIDED BY THE VEHICLE MANUFACTURER AT THE TIME OF MANUFACTURE AND MAY NOT BE ACCURATE OR COMPLETE. MANHEIM HAS NOT UNDERTAKEN STEPS TO CONFIRM THE ACCURACY OF ANY SUCH INFORMATION, AND ANY INFORMATION DISCLOSED HEREIN IS PROVIDED "AS IS".

Open All Packages Close All Packages

Charge Package - F01

OTHER OPTIONS

VIN: 1N4BZ0CP3HC307735, Work Order: 4060483