













 InSight Condition Report

2016 Volkswagen e-Golf 4dr HB SE

WVWKP7AU6GW911875 24,943 mi | Front Wheel Drive | Electric Motor | A/T | Hard Top | Cloth
 Lane/Run 49/252 Facilitation Manheim Riverside Seller VW CREDIT



 9 Damages	 ✓ No Structural Damage	 ✓ No Prior Paint	 4 2 4 4 Tires	 ✓ AutoCheck vehicle history reports Clean
 ✓ Drivable	 ✓ Starts	 ✓ No Odor	 4 Keys 2	 2 Fobs 2
 ? Title? (No Data)				



Announcements

- WTY 10/19

High Value Options

- | | | | |
|------------------------|----------------------------------|-------------------|-------------------------|
| • Back-Up Camera | • Heated Front Seat(s) | • Keyless Start | • Tire Pressure Monitor |
| • Bluetooth Connection | • Integrated Turn Signal Mirrors | • Multi-Zone A/C | |
| • Climate Control | | • Satellite Radio | |




Damage Overview



None ● ● ● Severe

● Structural Issue

Exterior (6)

Description	Condition Severity	Type	Image	Additional Info
● Windshield	Cracked < 1/8"	Miscellaneous		
● Front Bumper	Scraped GR 12"	Paint and Body Requires Conventional Repair		
● Hood	Chipped 10 or More	Paint and Body Requires Conventional Repair		
● LF Door	Dent/No Paint Dmg PDR/1	Cosmetic Conventional Paint and Body Not Required		
● Rear Bumper	Dent/No Paint Dmg < 1/8"	Paint and Body Requires Conventional Repair		
● RF Tire	Worn Replacement Required	Miscellaneous		

Interior (3)

Description	Condition Severity	Type	Image	Additional Info
● LF Seat	Stained Permanent	Interior		
● LR Seat/2nd Row	Stained Permanent	Interior		
● RR Seat/2nd Row	Stained Permanent	Interior		

Structure (0)

No structural damages reported

Other (0)


No other damages reported

Tires & Wheels

Wheels Aluminum

Left Front
BRIDGESTONE
4/32"
205/55R16.0

Left Rear
BRIDGESTONE
4/32"
205/55R16.0



Right Front
BRIDGESTONE
2/32"
205/55R16.0

Right Rear
BRIDGESTONE
4/32"
205/55R16.0

Spare
(None)
0/32"

- 6/32 +
- 5/32 to 4/32
- < 4/32
- N/A

History



No. of Historical Events 5
 Last Reported Event Date 05/11/2019
 Calculated Owners 1
 Last Reported Mileage 24,943
 Calculated Accidents 0

- Title and Problem Check ✔ Vehicle checks out!
- Odometer Check ✔ Vehicle checks out!
- Use and Event Check ! Specific vehicle use(s) or events reported
- AutoCheck Buyback Protection ✔ Qualifies

CARFAX

[View CARFAX](#)

Details

Exterior Color Blue	Title State CA	In Service Date Not Available
Interior Color Gray	Title Received 04/30/2019	Org Mfg Basic Warranty *3 Years/36,000 Miles
Top Type Hard Top	Received Date 04/25/2019	*Manheim is not responsible for voided warranties
Category Code LOI	Inspection Location Manheim Riverside	
MSRP \$31,625	Work Order 2894169	

Equipment

Options

- A/C
- Adjustable Steering Wheel
- AM/FM Stereo
- Automatic Headlights
- Auxiliary Audio Input
- CD Player
- Child Safety Locks
- Driver Adjustable Lumbar
- Driver Air Bag
- Driver Illuminated Vanity Mirror
- Driver Vanity Mirror
- Front Side Air Bag
- HD Radio
- Intermittent Wipers
- Passenger Adjustable Lumbar
- Passenger Air Bag
- Passenger Air Bag Sensor
- Passenger Illuminated Visor Mirror
- Passenger Vanity Mirror
- Power Door Locks
- Power Mirror(s)
- Power Steering
- Power Windows
- Rear Defrost
- Telematics
- Traction Control
- Trip Computer
- Variable Speed Intermittent Wipers

Interior

- Cloth
- Odometer Operable

Mechanical

- 0.0L None
- ABS Brakes
- Automatic Transmission
- Electric Fuel System
- Electric Motor
- Front Wheel Drive

Keys

- Master - 2
- Remote-Fob - 2

Manufacturer Info

Manufacturer Package Information

Information set forth herein is based solely on information provided by the vehicle manufacturer at the time of manufacture and may not be accurate or complete. Manheim has not undertaken steps to confirm the accuracy of any such information, and any information disclosed herein is provided "as is".

Options

Interior

- Remote Keyless Entry w/Integrated Key Transmitter, Illuminated Entry And Panic Button
- Heated Comfort Front Seats -inc: Manually Adjustable Front Seats w/Power Recline And Manual Lumbar Support
- Rigid Cargo Cover
- Perimeter Alarm
- Trip Computer
- Power Rear Windows
- Manual Tilt/Telescoping Steering Column
- Power 1st Row Windows w/Front And Rear 1-Touch Up/Down
- Vw Car-Net Selective Service Internet Access
- Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination
- Seats w/Cloth Back Material
- 2-Way Power Passenger Seat -inc: Power Recline, Manual Height Adjustment, Fore/Aft Movement
- And Manual Lumbar Support
- Fob Controls -inc: Trunk/Hatch/Tailgate
- 60-40 Folding Bench Front Facing Fold Forward Seatback Rear Seat
- Front Center Armrest And Rear Center Armrest w/Pass-Thru w/Storage
- Smart Device Integration
- Dual Zone Front Automatic Air Conditioning
- Immobilizer Iii Engine Immobilizer
- Cloth Seating Surfaces
- Gauges -inc: Speedometer, Odometer, Traction Battery Level, Power/Regen, Trip Odometer And Trip Computer
- Power Door Locks w/Autolock Feature
- Proximity Key For Doors And Push Button Start
- Full Carpet Floor Covering -inc: Carpet Front And Rear Floor Mats

Entertainment

- Radio: Composition Media w/6.5" Touchscreen -inc: AM/FM/HD Radio, CD w/USB Aux-in, 8-Speaker Sound System, Bluetooth Connectivity And SiriusXM Satellite Radio (Limited Subscription)
- Radio w/Seek-Scan, MP3 Player, Clock, Speed Compensated Volume Control And Radio Data System

Safety/Security

Exterior

- Speed Sensitive Rain Detecting Variable Intermittent Wipers w/Heated Jets
- Fully Automatic Aero-Composite Halogen Daytime Running Headlamps w/Delay-Off
- Tires: P205/55H16 AS BSW -inc: Low Rolling-Resistance
- Body-Colored Power Heated Side Mirrors w/Manual Folding And Turn Signal Indicator
- Tailgate/Rear Door Lock Included w/Power Door Locks
- Fixed Rear Window w/Fixed Interval Wiper And Defroster
- Wheels: 16" Astona Aerodynamic Alloy

Mechanical

- Brake Actuated Limited Slip Differential
- Electric Power-Assist Speed-Sensing Steering
- Transmission: Single-Speed Automatic
- Engine: 85KW 115HP Electric -inc: 24.2kWh Lithium-Ion Battery
- Front-Wheel Drive
- Regenerative 4-Wheel Disc Brakes w/4-Wheel ABS, Front Vented Discs, Brake Assist, Hill Hold Control And Electric Parking Brake

Other

- Vw Car-Net Emergency S.O.S
- Rear Child Safety Locks
- Side Curtain Protection Curtain 1st And 2nd Row Airbags
- ABS And Driveline Traction Control
- Back-Up Camera
- Low Tire Pressure Warning
- Airbag Occupancy Sensor
- Dual Stage Driver And Passenger Front Airbags
- Electronic Stability Control (Esc)
- Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- DC Fast Charging Package
- Cargo Area Luggage Net
- First Aid Kit

Vehicle condition reports contain representations made by the seller and subjective input based on inspector judgment, which may affect any AutoGrade score. The use of the report and any AutoGrade score is subject to the Manheim Terms and Conditions and the NAAA Generic Condition Report Position Statement.

This grade was calculated under the assumption that some repairs may be covered under manufacturer warranty.

† Damage Overview diagrams are not an exhaustive representation of vehicle damage and should be viewed in conjunction with the damage detail list on each tab.

*Process protected under U.S. Patent No. 8,320,362

VIN: VVWKP7AU6GW911875,

Work Order: 2894169

© 2019 Manheim. All Rights Reserved

[Return to the classic CR](#)