



InSight Condition Report

2016 Kia Soul EV 5dr Wgn +

KNDJX3AE4G7013251

20,497 mi | Front Wheel Drive | Electric Motor | A/T | Hard Top | Premium Synthetic

Lane/Run 2/144 Facilitation Manheim San Francisco Bay Seller KIA MOTORS FINANCE



AUTOGRADE
4.3
Clean

| | | | | |
|----------|----------------------|----------------|-----------|------------------|
| | | | | |
| Damages | No Structural Damage | No Prior Paint | Tires | Clean |
| | | | | |
| Drivable | Starts | No Odor | Keys 2 | Fobs 0 |
| | | | | |
| | | | | Title? (No Data) |



Announcements

- CHARGER/DMV\$210

High Value Options

- | | | | |
|------------------------|----------------------------------|------------------------|----------------------------|
| • Back-Up Camera | • Heated Front Seat(s) | • Keyless Start | • Rear Parking Aid |
| • Bluetooth Connection | • Heated Rear Seat(s) | • Multi-Zone A/C | • Satellite Radio |
| • Climate Control | • Heated Steering Wheel | • Navigation System | • Smart Device Integration |
| • Cooled Front Seat(s) | • Integrated Turn Signal Mirrors | • Premium Sound System | • Tire Pressure Monitor |
| • Fog Lamps | | • Privacy Glass | |


Damage Overview



None ● ● ● Severe

● Structural Issue

Exterior (2)

| Description | Condition Severity | Type | Image | Additional Info |
|---------------|-------------------------------|--|--|-----------------|
| ● L Qtr Panel | Dent/No Paint Dmg PDR/1 | Cosmetic Conventional Paint and Body Not Required | | |
| ● RR Door | Mult Dents/Paint Dmg 2 | Paint and Body Requires Conventional Repair |  | |

Interior (0)

No interior damages reported

Structure (0)

No structural damages reported

Other (0)


No other damages reported

Tires & Wheels

Wheels Aluminum

Left Front
 NEXEN
5/32"
 205/60R16.0

Left Rear
 NEXEN
7/32"
 205/60R16.0



Right Front
 NEXEN
5/32"
 205/60R16.0

Right Rear
 NEXEN
7/32"
 205/60R16.0

Spare
 (None)
0/32"

- 6/32 +
- 5/32 to 4/32
- < 4/32
- N/A

History



No. of Historical Events 6
 Last Reported Event Date 05/17/2019
 Calculated Owners 1
 Last Reported Mileage 20,497
 Calculated Accidents 0

- Title and Problem Check ✔ Vehicle checks out!
- Odometer Check ✔ Vehicle checks out!
- Use and Event Check ! Specific vehicle use(s) or events reported
- AutoCheck Buyback Protection ✔ Qualifies

CARFAX [View CARFAX](#)

Details

Exterior Color
Titanium Gray Metallic



Interior Color
Gray 2-Tone

Top Type
Hard Top

MSRP
Not Available

Title State
CA

Title Received
05/15/2019

Received Date
04/10/2019

Inspection Location
Manheim San Francisco
Bay

Work Order
2356391

In Service Date
Not Available

Org Mfg Basic Warranty
*5 Years/60,000 Miles
*Manheim is not
responsible for voided
warranties

Equipment

Options

- A/C
- Adjustable Steering Wheel
- AM/FM Stereo
- Auto-Dimming Rearview Mirror
- Automatic Headlights
- Auxiliary Audio Input
- Brake Assist
- Bucket Seats
- Cargo Shade
- Child Safety Locks
- Cruise Control
- Daytime Running Lights
- Driver Air Bag
- Driver Illuminated Vanity Mirror
- Driver Vanity Mirror
- Front Head Air Bag
- Front Side Air Bag
- Heated Mirrors
- Intermittent Wipers
- Keyless Entry
- Leather Steering Wheel
- MP3 Player
- Pass-Through Rear Seat
- Passenger Air Bag
- Passenger Air Bag Sensor
- Passenger Illuminated Visor Mirror
- Passenger Vanity Mirror
- Power Door Locks
- Power Folding Mirrors
- Power Mirror(s)
- Power Steering
- Power Windows
- Rear Bench Seat
- Rear Defrost
- Rear Head Air Bag
- Stability Control
- Steering Wheel Audio Controls
- Telematics
- Traction Control
- Trip Computer
- Variable Speed Intermittent Wipers

Interior

- Odometer Operable
- Premium Synthetic

Mechanical

- 0.0L None
- ABS Brakes
- Automatic Transmission
- Electric Fuel System
- Electric Motor
- Front Wheel Drive

Keys

- Smart - 2

Manufacturer Info

Manufacturer Package Information

Options

Interior

- Power Rear Windows And Fixed 3rd Row Windows
- Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination
- Trip Computer
- Proximity Key For Doors And Push Button Start
- Folding Cargo Cover
- Heated Leather Steering Wheel
- Gauges -inc: Speedometer, Odometer, Traction Battery Level, Power/Regen, Trip Odometer And Trip Computer
- Day-Night Auto-Dimming Rearview Mirror
- Engine Immobilizer
- Pure Leather Seat Trim -inc: Blue Piping
- Power Door Locks w/Autolock Feature
- Ventilated Front Bucket Seats
- Manual Tilt/Telescoping Steering Column
- Dual Zone Front Automatic Air Conditioning
- Integrated Navigation System w/Voice Activation
- 60-40 Folding Bench Front Facing Heated Fold Forward Seatback Rear Seat
- Remote Entry w/Integrated Key Transmitter And Panic Button
- Cruise Control w/Steering Wheel Controls
- Power 1st Row Windows w/Driver And Passenger 1-Touch Up/Down

Entertainment

- Bluetooth Wireless Phone Connectivity
- Radio w/Seek-Scan, Clock, Speed Compensated Volume Control, Steering Wheel Controls, Voice Activation And Internal Memory
- Radio: AM/FM/CD/MP3 Audio w/Navigation -inc: Illuminated USB/Auxiliary Port, UVO EV Services And SiriusXM Satellite Radio

Safety/Security

- Front And Rear Parking Sensors
- Rear Child Safety Locks
- Electronic Stability Control (Esc)
- Dual Stage Driver And Passenger Front

Exterior

- Variable Intermittent Wipers
- Wheels: 16" Alloy w/Full Wheel Covers
- Tailgate/Rear Door Lock Included w/Power Door Locks
- Deep Tinted Glass
- Tires: 205/60R16
- Fully Automatic Projector Beam
- Halogen Daytime Running Headlamps w/Delay-Off
- Fixed Rear Window w/Fixed Interval Wiper And Defroster
- Body-Colored Power Heated Side Mirrors w/Power Folding And Turn Signal Indicator
- Front Fog Lamps

Mechanical

- Engine: 109HP AC Electric Motor
- Lithium Ion Traction Battery w/6.6 kW Onboard Charger, 24 Hrs Charge Time @ 110/120V, 5 Hrs Charge Time @ 220/240V and 0.5 Hr Charge Time @ 440V
- Regenerative 4-Wheel Disc Brakes w/4-Wheel ABS, Front Vented Discs, Brake Assist, Hill Hold Control And Electric Parking Brake
- Transmission: 1-Speed Automatic
- Electric Power-Assist Speed-Sensing Steering
- Front-Wheel Drive

Other

- Paint Protection Film Package
- Carpeted Floor Mats

Airbags

- Back-Up Camera
- Low Tire Pressure Warning
- Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- Curtain 1st And 2nd Row Airbags
- ABS And Driveline Traction Control
- Emergency S.O.S
- Airbag Occupancy Sensor

Vehicle condition reports contain representations made by the seller and subjective input based on inspector judgment, which may affect any AutoGrade score. The use of the report and any AutoGrade score is subject to the Manheim Terms and Conditions and the NAAA Generic Condition Report Position Statement.

This grade was calculated under the assumption that some repairs may be covered under manufacturer warranty.

† Damage Overview diagrams are not an exhaustive representation of vehicle damage and should be viewed in conjunction with the damage detail list on each tab.

*Process protected under U.S. Patent No. 8,320,362

VIN: KNDJX3AE4G7013251,

Work Order: 2356391

© 2019 Manheim. All Rights Reserved

[Return to the classic CR](#)