



Learn More

Manheim Digital Marketplace
 Condition Report
 Atlanta, GA 30328
 (866)626-4346

VEHICLE DETAILS - 2017 NISSAN LEAF S

VIN: 1N4BZ0CP4HC308103	Body Style: 4DHB	Top Type: Hard Top
Ext Color: GREY	Int Color: Bla- BLK	Odometer: 24,425
Work Order: 4122004	Seller: NISSAN MOTOR CORPORATION	Received Date: N/A
InService Date: N/A		



GRADING



Grade 4.5 Clean

- MSRP-0 ???.
- Drivable-Yes

*Process protected under U.S. Patent No. 8,320,362

VALUE ADDED OPTIONS

- Bluetooth Connection
- Heated Seats-Front(s)
- MP3 Compatible Stereo
- Satellite Radio

VEHICLE INFORMATION

OPTIONS

- | | | | |
|---|---|--|--|
| <ul style="list-style-type: none"> ■ A/C ■ ABS Brakes ■ AM/FM Stereo ■ Automatic Headlights ■ Back up Camera ■ Brake Assist System ■ Bucket Seats ■ CD Player | <ul style="list-style-type: none"> ■ Child Safety Locks ■ Cruise Control ■ Electronic Stability Control ■ Engine Immobilizer ■ Front Floor Mats ■ Intermittent Wipers ■ Keyless Entry ■ Keyless Start | <ul style="list-style-type: none"> ■ Pass-Through Rear Seat ■ Power Mirrors ■ Power Windows ■ Pwr Steering ■ Rear Floor Mats ■ Rear Spoiler ■ Security System ■ Steering Wheel Audio Control | <ul style="list-style-type: none"> ■ Tilt Steering ■ Tire Pressure Monitor System ■ Traction Control ■ Trip Computer ■ Wheel Covers |
|---|---|--|--|

MECHANICAL

- Engine Type - Non
- Automatic
- 4X2

INTERIOR

- Odometer - 6 Digits Digital -Operable
- Cloth - BLK
- Int Odor: OK

TIRES AND WHEELS

Wheels:

Tire	Tread Depth	Brand	Size
Left Front:	6/32"	Bridgestone	205/55R16
Left Rear:	7/32"	Bridgestone	205/55R16
Right Front:	6/32"	Bridgestone	205/55R16
Right Rear:	6/32"	Bridgestone	205/55R16
Spare:	10/32"	Other	255/30R18

KEYS

- Smart Key - 2

OTHER

- Title State:
- Title Received Date: N/A

ADDITIONAL INFORMATION

DAMAGE SUMMARY AND ADDITIONAL IMAGES

Open All Damages Close All Damages

Cosmetic Conventional Paint and Body Not Required-[1 Items]

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	RF Door	Dent/No Paint Dmg	PDR/1

Miscellaneous-[3 Items]


















IMAGE	DESCRIPTION	CONDITION	SEVERITY
	LF Wheel Cover	Broken	Replacement Required
	Tire Inflator	Missing	Replacement Required
	Windshield	Cracked	< 1/8"

IMAGE	DESCRIPTION	CONDITION	SEVERITY
-------	-------------	-----------	----------

	0000 Picture# 1	Overall Picture	
	0000 Picture# 2	Overall Picture	
	0000 Picture# 3	Overall Picture	
	0000 Picture# 4	Overall Picture	
	0000 Picture# 5	Overall Picture	
	0000 Picture# 6	Overall Picture	
	0000 Picture# 7	Overall Picture	
	0000 Picture# 8	Overall Picture	
	0000 Picture# 9	Overall Picture	
	0000 Picture# 10	Overall Picture	
	0000 Picture# 11	Overall Picture	
	0000 Picture# 12	Overall Picture	
	0000 Picture# 13	Overall Picture	
	0000 Picture# 14	Overall Picture	
	0000 Picture# 15	Overall Picture	



0000 Picture# 16

Overall Picture



0000 Picture# 17

Overall Picture



0000 Picture# 18

Overall Picture

0000 Picture# 19

Overall Picture

0000 Picture# 20

Overall Picture

0000 Picture# 21

Overall Picture

0000 Picture# 22

Overall Picture

0000 Picture# 23

Overall Picture

MANUFACTURER PACKAGE INFORMATION

INFORMATION SET FORTH HEREIN IS BASED SOLELY ON INFORMATION PROVIDED BY THE VEHICLE MANUFACTURER AT THE TIME OF MANUFACTURE AND MAY NOT BE ACCURATE OR COMPLETE. MANHEIM HAS NOT UNDERTAKEN STEPS TO CONFIRM THE ACCURACY OF ANY SUCH INFORMATION, AND ANY INFORMATION DISCLOSED HEREIN IS PROVIDED "AS IS".

Open All Packages Close All Packages

Charge Package - F01

OTHER OPTIONS

VIN: 1N4BZ0CP4HC308103, Work Order: 4122004